

**Fairfield Locations Suspected to Have Received Julian Fill (2013-2016)**  
**Julian Fill Location List**  
**October 7, 2020**

Site	Location	<10 Cubic Yards <sup>1</sup>	"Clean Fill" Used Based on Results <sup>2</sup>	Remediation Required <sup>3</sup>	Remediation Completed
Burroughs	Soccer Field 1	x <sup>7</sup>		Yes	Yes
Fairfield Ludlowe High School	Courtyard	x <sup>7</sup>		Yes	
Gould Manor Park	Sidewalk Installation			Yes	Yes <sup>10</sup>
Hillside Road	Curb Installation			Yes <sup>9</sup>	
Jennings Beach	Area around water line replacement	x		Yes <sup>8</sup>	
	Playground Grass Area	x <sup>7</sup>		Yes <sup>8</sup>	
Lake Mohegan	Trail Head Repair	x		Yes	
Mill Hill Elementary School	ADA Sidewalk Installation			Yes <sup>8</sup>	
Old Dam Road	Area behind building and tennis courts			Yes <sup>8</sup>	
Osborn Hill Elementary School	Drainage repair	x		Yes <sup>8</sup>	
Penfield Pavilion	Parking Lots and Building Area			Yes	
Perry Street	Open Space Trail			Yes	
Southport Beach	Curb Repair	x		Yes <sup>8</sup>	
Sunset Avenue	Curb Installation	x <sup>7, 9</sup>		Yes <sup>8</sup>	
Beach Road	Walkway	x		FI	
Fire Training Center	Under Burn Building			FI	
	Under Tank			FI	
	Under Stormwater System			FI	
Frank Rice Senior Trail/Oldfield/Old Dam Rd Open Space	Open Space Trail			FI	
Hoydens Hill Area	Barn at the Shooting Range			FI	
	Trail			FI	
	Shooting Range			FI	
McKinley Elementary School	Soccer Field and Former Playground Area			FI <sup>8</sup>	
Mill Hill Road	Sidewalk Installation			FI <sup>9</sup>	
Stratfield Road	Tree Repair	x <sup>7</sup>		FI	
Burr Elementary School	Soccer Field	x <sup>7</sup>	x	No	NR
Burroughs	Soccer Field 2	x <sup>7</sup>	x	No	NR
Coral Drive	Drainage repair		x	No	NR
Dougello Field	Softball Field		x	No	NR
Dwight Elementary School	Soccer	x <sup>7</sup>	x	No	NR
Fairfield Ludlowe High School	Practice Fields (Sturges)	x <sup>7</sup>	x	No	NR
Fairfield Woods Middle School	Lower Soccer Field	x <sup>7</sup>	x	No	NR
	Upper Soccer Field	x <sup>7</sup>	x	No	NR
	Parking Area/Plantings Area		x	No	NR
High Ridge Road	Drainage repair		x	No	NR
Holland Hill Elementary School	Soccer Field	x <sup>7</sup>	x	No	NR
Jennings Elementary School	Soccer Field	x <sup>7</sup>	x	No	NR
North Stratfield Elementary School	Soccer Field	x <sup>7</sup>	x	No	NR
Oldfield School	Soccer Field	x <sup>7</sup>	x	No	NR
Osborn Hill Elementary School	Baseball Field	x	x	No	NR
Riverfield Elementary School	Baseball Field 1 (near Hunter Road/Gym)		x	No	NR
	Baseball Field 2 (near Playscape)		x	No	NR
	Grass Area near Parking Lot		x	No	NR
Ronald Drive	Curb Installation		x <sup>9</sup>	No	NR
Samp Mortar	Catch basin repair	x	x <sup>9</sup>	No	NR
Senior Center Job	Gazebo and Patio Installation		x	No	NR
Smith Richardson	Cart Path and Driveway Repair		x <sup>9</sup>	No	NR
South Pine Creek Rec. Area	Football (Sullivan/Multipurpose)	x <sup>7</sup>	x	No	NR
	Soccer Field 1	x <sup>7</sup>	x	No	NR
Tomlinson Middle School	Back Drainage repair	x	x <sup>9</sup>	No	NR
	Front Drainage Repair	x	x	No	NR
Town Hall	Soccer Field	x <sup>7</sup>	x	No	NR
Tunxis Hill	Soccer/Baseball Field	x <sup>7</sup>	x	No	NR
Ye Yacht Yard	Curb Repair	x <sup>9</sup>	x	No	NR

**Footnotes:**

1. See Connecticut General Statute § 22a-207(6) (excluding locations used for the disposal of less than or equal to ten cubic yards of solid waste from the definition of "solid waste disposal area").
2. See Regulations of Connecticut State Agencies (RCSA) § 22a-209-1 (defining "clean fill"); see also RCSA § 22a-209-3 (exempting areas, which are solely for disposal of "clean fill," from solid waste regulatory requirements).
3. Unless an alternative criteria is requested of and approved by DEEP, Julian Fill locations will be remediated in general accordance with the Residential Direct Exposure Criteria set forth in Connecticut's Remediation Standard Regulations, RCSA §§ 22a-133k-1 et seq.
4. FI - Further Investigation Required
5. NR - Not Required
6. Shaded gray cells indicate <10 cubic yards of Julian fill and/or "Clean Fill" Used Based on Results.
7. Based on the Town's research, Julian Fill was placed at the location but no invoice or other document indicating the quantity was available.
8. RAP submitted to the DEEP for review and comment.
9. PAHs not sampled due to presumed interferences and background concentrations of PAHs from asphalt roadways and parking lots. Julian Fill inaccessible under the pavement.
10. Known Julian Fill has been remediated. Awaiting DEEP approval of alternative REC DEC for PAHs.