

ENVIRONMENTAL TESTING SCORECARD

Type*	Location	Specific Area	Status	Being Evaluated for Remediation?	Aggregate Fill Used?	Tested by Town	Tested by FPS
S	Burr Elementary School	Playscape	Open	No	No record of Aggregate Fill at this location		X
S	Burr Elementary School	Small Playscape	Open	No	No record of Aggregate Fill at this location		x
S	Burr Elementary School	Soccer Field	Open	No	Yes/Aggregate Fill is likely to have been used at this location	X	
S	Burr Elementary School	Swing Area	Open	No	No record of Aggregate Fill at this location		x
S	Dwight Elementary School	Baseball Field	Open	No	No record of Aggregate Fill at this location	X	
S	Dwight Elementary School	Playscape	Open	No	No record of Aggregate Fill at this location		X
S	Dwight Elementary School	Soccer Field	Open	No	Yes/Aggregate Fill is likely to have been used at this location	X	
S	Fairfield Ludlowe High School	Courtyard	Open - Partial Restrictions	Yes	Yes/Aggregate Fill is likely to have been used at this location		x
S	Fairfield Ludlowe High School	Front Field	Open	No	No record of Aggregate Fill at this location		X
S	Fairfield Ludlowe High School	Practice Field (Sturges)	Open	No	Yes/Aggregate Fill is likely to have been used at this location		X
S	Fairfield Ludlowe High School	Softball Field (Sturges)	Open	No	No record of Aggregate Fill at this location		X
S	Fairfield Warde High School	Front Field	Open	No	No record of Aggregate Fill at this location		X
S	Fairfield Warde High School	Practice Field	Open	No	No record of Aggregate Fill at this location		X
S	Fairfield Warde High School	Softball Field	Open	No	No record of Aggregate Fill at this location		X
S	Fairfield Woods Middle School	Baseball	Open	No	No record of Aggregate Fill at this location	X	
S	Fairfield Woods Middle School	Lower Soccer Field	Open	No	Yes/Aggregate Fill is likely to have been used at this location	X	
S	Fairfield Woods Middle School	Parking Area/Plantings Area	Open	No	Yes/Aggregate Fill is likely to have been used at this location	X	
S	Fairfield Woods Middle School	Upper Soccer Field	Open	No	Yes/Aggregate Fill is likely to have been used at this location	X	
S	Holland Hill Elementary School	Playscape	Open	No	No record of Aggregate Fill at this location		X
S	Holland Hill Elementary School	Playscape close to Soccer Field	Open	No	No record of Aggregate Fill at this location		X
S	Holland Hill Elementary School	Soccer Field	Closed Due to Construction	No	Yes/Aggregate Fill is likely to have been used at this location	X	
S	Jennings Elementary School	Playscape near Soccer Field	Closed	Yes	No record of Aggregate Fill at this location	X	X
S	Jennings Elementary School	Small Playscape	Closed	Yes	No record of Aggregate Fill at this location		X
S	Jennings Elementary School	Soccer Field	Open	No	Yes/Aggregate Fill is likely to have been used at this location	X	
S	McKinley Elementary School	Grass Area where former Playscape was	Closed	Yes	No record of Aggregate Fill at this location		x
S	McKinley Elementary School	Playscape	Open	No	No record of Aggregate Fill at this location		X
S	McKinley Elementary School	Soccer Field	Open	No	Yes/Aggregate Fill is likely to have been used at this location	X	

ENVIRONMENTAL TESTING SCORECARD

Type*	Location	Specific Area	Status	Being Evaluated for Remediation?	Aggregate Fill Used?	Tested by Town	Tested by FPS
S	Mill Hill Elementary School	Playscape	Open	No	No record of Aggregate Fill at this location		x
S	Mill Hill Elementary School	Walkway to Playscape	Closed	Yes	Yes/Aggregate Fill is likely to have been used at this location	X	
S	North Stratfield Elementary School	Playscape near Soccer Field	Open	No	No record of Aggregate Fill at this location		x
S	North Stratfield Elementary School	Soccer Field	Open	No	Yes/Aggregate Fill is likely to have been used at this location	X	X
S	North Stratfield Elementary School	Front Planting Area	Open	No	No record of Aggregate Fill at this location		x
S	North Stratfield Elementary School	Playscape	Open	No	No record of Aggregate Fill at this location		X
S	Osborn Hill Elementary School	Baseball Field	Open - Partial Restrictions	Pending	Yes/Aggregate Fill is likely to have been used at this location	X	X
S	Osborn Hill Elementary School	Playscape	Open	No	No record of Aggregate Fill at this location		X
S	Riverfield Elementary School	Baseball Field 1(near Hunter Road/Gym)	Open	No	No record of Aggregate Fill at this location but work done within time period in question	X	
S	Riverfield Elementary School	Baseball Field 2 (near Playscape)	Open	No	No record of Aggregate Fill at this location but work done within time period in question	X	
S	Riverfield Elementary School	Grass Area near Parking Lot	Open	No	No record of Aggregate Fill at this location but work done within time period in question	X	
S	Riverfield Elementary School	Playscape	Open	No	No record of Aggregate Fill at this location	X	X
S	Roger Ludlowe Middle School	Soccer Field 1	Open	No	No record of Aggregate Fill at this location		X
S	Roger Ludlowe Middle School	Soccer Field 2	Open	No	No record of Aggregate Fill at this location		X
S	Roger Sherman Elementary School	Playscape	Open	No	No record of Aggregate Fill at this location		X
S	Roger Sherman Elementary School	Soccer	Open	No	No record of Aggregate Fill at this location		X
S	Roger Sherman Elementary School	Softball	Open	No	No record of Aggregate Fill at this location		X
S	Stratfield Elementary School	Front Playscape	Open	No	No record of Aggregate Fill at this location		X
S	Stratfield Elementary School	Grass Space	Open	No	No record of Aggregate Fill at this location		X
S	Stratfield Elementary School	Playscape near Parking Lot	Open	No	No record of Aggregate Fill at this location		X
P	Burroughs	Soccer Field 1	Open - Partial Restrictions	Yes	Yes/Aggregate Fill is likely to have been used at this location	X	
P	Burroughs	Soccer Field 2	Open	No	Yes/Aggregate Fill is likely to have been used at this location	X	
P	Dougiello	Softball	Open	No	Yes/Aggregate Fill is likely to have been used at this location	X	
P	Gould Manor Park	Sidewalk Area	Open - Remediation in Progress	Yes	Yes/Aggregate Fill is likely to have been used at this location	X	
P	Jennings Beach	Area around Water line replacement	Open - Partial Restrictions	Yes	Yes/Aggregate Fill is likely to have been used at this location	X	

ENVIRONMENTAL TESTING SCORECARD

Type*	Location	Specific Area	Status	Being Evaluated for Remediation?	Aggregate Fill Used?	Tested by Town	Tested by FPS
P	Jennings Beach	Playground Grass Area	Open - Partial Restrictions	Yes	Yes/Aggregate Fill is likely to have been used at this location	X	
P	Old Dam Road	Area Behind Building/Tennis Courts	Open - Partial Restrictions	Yes	Yes/Aggregate Fill is likely to have been used at this location	X	
P	Oldfield School	Soccer Field	Open	No	Yes/Aggregate Fill is likely to have been used at this location	X	
P	South Pine Creek Rec. Area	Baseball (Kiwanis)	Open	No	No record of Aggregate Fill at this location	x	
P	South Pine Creek Rec. Area	Football (Sullivan/Multipurpose)	Open	No	Yes/Aggregate Fill is likely to have been used at this location	X	
P	South Pine Creek Rec. Area	Soccer Field 1	Open	No	Yes/Aggregate Fill is likely to have been used at this location	X	
P	Town Hall	Soccer	Open	No	Yes/Aggregate Fill is likely to have been used at this location	X	
P	Tunxis Hill	Soccer/Baseball	Open	No	Yes/Aggregate Fill is likely to have been used at this location	X	
* S = School; P = Park							